735

SERVICE NOTES

O-RING - REF. 219

Early units were produced with O-Ring 879449 Ref. 219 to help retain the Carrier Tube Ref. 150. It has been determined that the Carrier Tube Retaining Screws Ref. 187 provide more than adequate support and the O-Ring has been eliminated. When servicing early units you should discard the O-Ring Ref. 219 and reassemble the unit without it.