Supplement Sheet

Date: November 15, 2011
Subject: Warranty Statement

Model(s): 316.79440 (41ADZ21C799)

This Warranty Sheet supersedes any warranty that is on the packaging or in your operator's manual.

WARRANTY

CRAFTSMAN TWO YEAR FULL WARRANTY

FOR TWO YEARS from the date of purchase, this product is warranted against any defects in material or workmanship. A defective product will receive free repair or replacement if repair is unavailable.

ADDITIONAL LIMITED WARRANTY ON TRIMMER SHAFTS

FOR THE THIRD THROUGH TENTH YEAR from the date of purchase, the outer metal housing of the upper and lower trimmer shafts is warranted against any defects in material or workmanship. With proof of purchase, a new housing will be supplied free of charge. You are responsible for the labor cost of installation. This additional coverage does not apply to inner trimmer shaft components.

For warranty coverage detail to obtain free repair or replacement, visit the web site: www.craftsman.com This warranty covers ONLY defects in material and workmanship. Warranty coverage does NOT include:

- · Expendable items that can wear out from normal use within the warranty period, such as cutting line, spark plugs, or filters.
- · Product damage resulting from user attempts at product modification or repair or caused by product accessories.
- · Repairs necessary because of accident or failure to operate or maintain the product according to all supplied instructions.
- · Preventive maintenance, or repairs necessary due to improper fuel mixture, contaminated or stale fuel.

This warranty is void if this product is ever used while providing commercial services or if rented to another person.

This warranty gives you specific legal rights, and you may also have other rights which vary from state to state.

Sears Brands Management Corporation, Hoffman Estates, IL 60179

FOR IN-WARRANTY SAFETY, OPERATION OR MAINTENANCE QUESTIONS, OR TO ORDER PARTS AND SCHEDULE SERVICE, CALL 1-800-4-MY-HOME®

Sears Brands Management Corporation, Hoffman Estates, IL 60179 U.S.A.

Printed In USA (November 15, 2011)